



# Board of Commissioners of Cook County

118 North Clark Street  
Chicago, IL

## Legislation Details (With Text)

**File #:** 18-5449      **Version:** 1      **Name:** Edwards Engineering, Inc., Elk Grove Village, Illinois  
**Type:** Payment Approval      **Status:** Approved  
**File created:** 8/22/2018      **In control:** Board of Commissioners  
**On agenda:** 9/26/2018      **Final action:** 9/26/2018  
**Title:** PROPOSED PAYMENT APPROVAL

Department(s): Department of Capital Planning and Policy

Action: Request to Approve Payment

Payee: Edwards Engineering, Inc., Elk Grove Village, Illinois

Good(s) or Service(s): Construction Services

Fiscal Impact: \$75,680.60

Accounts: Capital Improvement Program-580

Contract Number(s): 1355-12950

Summary: This payment is for services rendered to address mechanical issues with the clean steam system at John H. Stroger Jr. Hospital. A number of air handling units were causing mechanical issues with detectors located within the ducts and the sensors were required to be relocated to resolve the issue.

This request for payment is being made because the invoice for services rendered was submitted after the contract had expired. A release on the remaining contract funds to pay the invoice had not been created prior to the contract's termination date.

**Sponsors:**

**Indexes:** EARL MANNING, Director, Office of Capital Planning and Policy

**Code sections:**

**Attachments:**

Date	Ver.	Action By	Action	Result
9/26/2018	1	Board of Commissioners	approve	Pass

### PROPOSED PAYMENT APPROVAL

**Department(s):** Department of Capital Planning and Policy

**Action:** Request to Approve Payment

**Payee:** Edwards Engineering, Inc., Elk Grove Village, Illinois

**Good(s) or Service(s):** Construction Services

**Fiscal Impact:** \$75,680.60

**Accounts:** Capital Improvement Program-580

**Contract Number(s):** 1355-12950

**Summary:** This payment is for services rendered to address mechanical issues with the clean steam system at John H. Stroger Jr. Hospital. A number of air handling units were causing mechanical issues with detectors located within the ducts and the sensors were required to be relocated to resolve the issue.

This request for payment is being made because the invoice for services rendered was submitted after the contract had expired. A release on the remaining contract funds to pay the invoice had not been created prior to the contract's termination date.